

■ 標準寸法一覧表

製品コード番号(内径×長さ)でご指示下さい。(例)MDB 05-05

プッシュ 内径 φd	適用寸法(mm)			プッシュ長さ(L) 公差0~-0.2															
	軸 寸法 公差hr	ハウジング 寸法 公差hr	外径 φD 公差	5	6	8	10	12	15	20	25	30	35	40	50	60	70	80	95
				MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR	MDR
5	5 0~-0.012	7 +0.015~0	7 +0.055~+0.025	05-05		05-08													
6	6 "	8 "	8 "		06-06		06-10												
7	7 0~-0.015	9 "	9 "					07-12											
8	8 "	10 "	10 "			08-08	08-10	08-12	08-15										
9	9 "	11 +0.018~0	7 +0.060~+0.030				09-10												
10	10 "	12 "	12 "				10-10		10-15	10-20									
12	14 0~-0.018	10 "	10 "				12-10		12-15	12-20									
13	13 "	15 "	15 "																
14	14 "	16 "	16 +0.065~+0.035				14-10		14-15	14-20									
15	15 "	17 "	17 "				15-10		15-15	15-20	15-25								
16	16 "	18 "	18 +0.070~+0.035						16-15	16-20	16-25								
17	17 "	19 +0.021~0	19 "																
18	18 "	20 "	20 +0.075~+0.040						18-15		18-25								
20	20 0~-0.021	23 "	23 +0.050~+0.045						20-15	20-20	20-25	20-30							
22	22 "	25 "	25 "							22-20		22-30							
24	24 "	27 "	27 "									24-30							
25	25 "	28 "	28 +0.065~+0.060						25-15	25-20	25-25	25-30	25-35						
26	26 "	30 "	30 "									26-30							
28	28 "	32 +0.025~0	32 +0.090~+0.050							28-20		28-30		28-40					
30	30 "	34 "	34 "						30-15	30-20		30-30	30-35	30-40					
31	31 "	35 "	35 "											31-40					
32	32 "	36 "	36 "							32-20				32-40					
35	35 "	39 "	39 +0.095~+0.055									35-30		35-40	35-50				
38	38 "	42 "	42 "									38-30			38-50				
40	40 "	44 "	44 "									40-30		40-40	40-50				
42	42 "	47 "	47 "												42-50				
45	45 "	50 "	50 +0.100~+0.060									45-30			45-50				
50	50 "	55 +0.030~0	55 +0.105~+0.060									50-30		50-40	50-50	50-60			
55	55 0~-0.030	60 "	60 +0.110~+0.065											55-40			55-70		
60	60 "	65 "	65 +0.120~+0.070											60-40		60-60			
65	65 "	70 "	70 +0.125~+0.075											65-40		65-60			
70	70 "	75 "	75 "											70-40				70-80	
75	75 "	80 "	80 +0.130~+0.075											75-40				75-80	
80	80 "	85 +0.035~0	85 "											80-40				80-80	
85	85 0~-0.035	90 "	90 "											85-40				85-80	
90	90 "	95 "	95 "											90-40		90-60			
100	100 "	105 "	105 +0.140~+0.080												100-50				100-95